

MONTHLY OPERATIONS REPORT December 2017

Town of Discovery Bay, CA
3046 Days of Safe Operations
146,188 worked hours since last recordable incident

TRAINING: Safety, Operations, & Equipment

- * TRAINING:
- • Safety
 - West Monthly Regional Safety Webinar(cancelled)
 - Eye Injuries
 - Excavation

- Operation
 - None this Month

REPORTS SUBMITTED TO REGULATORY AGENCIES

- Monthly Discharge Monitoring Report (DMR)
- * Monthly electronic State Monitoring Report (eSMR)
- * Monthly Coliform Report, State Water Board (WD)

WATER SERVICES

Groundwater Well:

- 1B Active
- 2 Active
- 4 Active
- 5B Active (Standby only)
- 6 Active
- 7 Active


2017 Water Production Table (MG) by Month

January	February	March	April	May	June
40	33	44	56	105	113
July	August	September	October	November	December
127	122	104	87	48	47

Bacteriological Test Results

Routine Bacteria	No. Total Coliform	No. Fecal/E. coli	Brown Water	Fire Hydrant
Samples Collected	Positives	Positives	Calls	Flushing
• 16	• 0	• 0	• 0	• 5


WATER USAGE



Water Saved



Chemical Usages



WASTEWATER SERVICE

Wastewater Laboratory Analysis

WW Effluent Parameter	Permit Limits	Nov Lab Data	Dec Lab Data
Flow, MG Effluent, monthly total		34	34
Flow, MG Daily Influent Flow, avg.	N/A	1.3	1.3
Flow, MG Daily Discharge Flow, avg.	2.1	1.2	1.1
Effluent BOD ₅ , lbs/d, monthly avg .	350	14	20
Effluent TSS, lbs/d, monthly avg.	525	8	12
Effluent BOD ₅ , mg/L, monthly avg .	20	2	2*
Effluent TSS, mg/L, monthly avg.	30	1	1
Total Coli form 7 day Median Max	23	ND	ND
Total Coli form Daily Maximum	240	17	ND
% Removal BOD ₅ , monthly avg.	85% min.	99	99
% Removal, TSS, monthly avg.	85% min.	98	99
Electrical Conductivity, umhos/cm annual avg.	2100	2100	2100

^{* 1} test was bad

WASTEWATER SERVICE

National Pollution Discharge Elimination System (NPDES)

NPDES Related	Permit Parameter	NPDES Parameter	Actual Parameter
Excursions		Limit	Result
• 0	• N/A	• N/A	• N/A

COLLECTION:

# of Active # of Inactive Lift Stations Lift Stations		SSO Wastewater Received (MG)	
15	0	0*	34

Force Main Vortox boxat Golf Station had a big rag ball that caused sewer to come out of top.

WASTEWATER SERVICE


- * 255,700 ft. of collection sewer line has been assessed
- * o ft. flushed/CCTV
- * 593 manhole & cover has been inspected
- Performed weekly lift station inspections.

Maintenance

Preventive and Corrective



Work Order Back-Log



General Info

Call & Emergency Responses

Call Outs Emergencies

2

Personnel Hours & Overtime:

Regular Hours Overtime

1680

TERMS

WWTP WASTEWATER TREATMENT PLANT

WTP WATER TREAMENT PLANT

WL WILLOW LAKE

NP NEWPORT

VFD VARIABLE FREQUENCY DRIVE

WO WORK ORDER

PLC PROGRAMMABLE LOGIC CONTROLLER

L/S LIFT STATION

SSO SANITARY SEWER OVERFLOW

BOD BIOLOGICAL OXYGEN DEMAND

TSS TOTAL SUSPENDED SOLIDS

MGD MILLION GALLONS PER DAY

mg/I MILLIGRAMS PER LITRE

CCTV CLOSED CIRCUIT TELEVISION

PPM PARTS PER MILLION

RAS RETURN ACTIVATED SLUDGE

WAS WATSE ACTIVATED SLUDGE

UV ULTRAVIOLET LIGHT

Force main Vortex box

